

The largest shares in the history of paging

Ford Motor Co.. plans to engage in "action paging" owners 4.5 million vehicles due to the dripping speed limiter sensor. The problem, among others, Windstar models from the years 1995 -2003.

Although there was no such case, the American producer wants to avoid the risk of fire, which is theoretically possible as a result of sensor failure, produced by Texas Instruments, which may manifest as its overheating or ignition. In addition to the Windstar model, ill-fated element was mounted in many American pickup or SUV such their versions of Explorer or Ranger. Official channels to be able to get a few, several pieces of such cars. Is unknown and the number of such models, which were brought in the private import.